

HEADQUARTERS

98 ARCH. MAKARIOU AVE, OFFICE 101 2224 LATSIA, NICOSIA, CYPRUS

> T: +357 22486452 F: +357 22487427

E: NORTEST@NORTEST.COM.CY W: WWW.NORTEST.COM.CY

"your partner in quality"

Certificate of Conformity Unit Verification Report

According to standard EN 13445-5:2014+A1:2018 and Pressure Equipment Directive 2014/68/EU - **Module G**

| Notification No. of the Certification body: | 2338 | Certificate No: | SOR00008739_02 |
|---|----------------------|------------------|----------------|
| Reference (checklist) coded: | F-QCP 3310/2E_ | Audit Report No: | 2024_10002 |
| | PED_Checklist Mod. G | Audit Date: | 31/03/2024 |

| Pressure Vessel Details | | | |
|--------------------------------------|-----------------------------------|------------------------------------|-------------------|
| Owner: | ENGIPLAS ENGINEERING PLASTICS LTD | | |
| Pressure Vessel: | 1217 | Category: | IV |
| Description: | OLEUM REACTION POT | Conformity assessment module used: | - |
| | | General arrangement drawing No.: | 4202 1450-412 171 |
| Volume (L): | 700 | Year of manufacture: | 2023 |
| Maximum allowable pressure [bar(g)]: | 1 | Safety valves: | - |
| Maximum allowable temperature (°C): | 170 | Capacity (m³): | - |
| Minimum allowable temperature (°C): | Room Temp. | Set pressure [bar(g)]: | - |
| Contents: | LIQUID | Corrosion allowance (mm): | 0 |

| Test Details | | | |
|--------------------------|------------|-------------------------|---|
| Pressure testing medium: | WATER | Test pressure [bar(g)]: | 1.43 |
| Type of inspection: | HYDROTEST | Inspection time: | 30min |
| Inspection date: | 31/03/2024 | Next inspection date: | AC.TO LOCAL REGULATIONS (MAX 5 YEARS) |

| Design of the Pressure Vessel | | | |
|-------------------------------|--------------------------|---------------------|---------------------------------------|
| Responsible Authority: | GERBER ENGINEERING REG'D | Name: | Gerber Felix |
| | | Address: | Yehuda Perah Str 10 Netanya Israel |
| | | Identification No.: | - |
| Design approval: | - | Number: | - |
| | | Date: | - |



HEADQUARTERS

98 ARCH. MAKARIOU AVE, OFFICE 101 2224 LATSIA, NICOSIA, CYPRUS

> T: +357 22486452 F: +357 22487427

E: NORTEST@NORTEST.COM.CY W: WWW.NORTEST.COM.CY

"your partner in quality"

| Manufacture and Inspection | | | |
|----------------------------|--------------------------------------|---------------------|---|
| Responsible Authority: | ENGIPLAS ENGINEERING PLASTICS LTD | Name: | IDO SHIMON |
| | | Address: | INDUSTIAL ZONE P.O. 125 37101 PARDES HANA, ISRAEL |
| | | Identification No.: | 38297222 |
| Certificate: | - | Number: | - |
| | | Date: | 25/07/2024 |

| Quality System | | | |
|--------------------------------|--------------------------------------|---------------------|---|
| Responsible Authority: | ENGIPLAS ENGINEERING PLASTICS LTD | Name: | BORIS KOMISARCHUK |
| | | Address: | INDUSTIAL ZONE P.O. 125 37101 PARDES HANA, ISRAEL |
| System assessment certificate: | | Identification No.: | 313022113 |
| | | Date: | 25/07/2024 |

The underdesigned declares that the design, manufacture and inspection of this pressure vessel is in compliance with the requirements of EN 13445.

Name:

CHRISTOS KALLIS

Date issued:

REVIEWED BY

Position:

Company stamp:

NSPECTION AND CERTIFICATION

END OF CERTIFICATE

This certificate may not be reproduced other than in full, except with the prior written approval of both Nortest Cyprus Ltd and the issuing manufacturer.